⚠ WARNING

Arc Flash and Shock Hazard. Appropriate PPE Required!

DISC_COMPLEX (WC)

39.4 cal/cm^2 @18 in		**29.97 kA**	Fault Current
160 in	Arc Flash Boundary	**0.993 sec**	Trip Time
415 VAC	Shock Hazard		
42 in	Limited Approach		
12 in	Restricted Approach		
00	Glove Class		

SHAW
CONSULTING SERVICES, LLC

WWW.SHAWENGR.COM

Minimum PPE Requirements:

Clothing with an arc-rating > the incident energy. Long-sleeve shirt + pants or coverall or arc flash suit. Arc-rated arc flash suit hood. Arc rated outerwear as needed. Arc-rated gloves, Hard hat, Safety glasses or goggles, Hearing protection, Leather footwear.

04/23/2026

SHAW CONSULTING SERVICES, LLC. (470) 641-2562

⚠ WARNING

Arc Flash and Shock Hazard. Appropriate PPE Required!

DISC_FAN (WC)

13.2 cal/cm^2 @18 in		**5.48 kA**	Fault Current
81 in	Arc Flash Boundary	**2.000 sec**	Trip Time
415 VAC	Shock Hazard		
42 in	Limited Approach		
12 in	Restricted Approach		
00	Glove Class		

SHAW CONSULTING SERVICES, LLC

WWW.SHAWENGR.COM

Minimum PPE Requirements:

Clothing with an arc-rating > the incident energy. Long-sleeve shirt + pants or coverall or arc flash suit. Arc-rated arc flash suit hood. Arc rated outerwear as needed. Arc-rated gloves, Hard hat, Safety glasses or goggles, Hearing protection, Leather footwear.

04/23/2026

SHAW CONSULTING SERVICES, LLC. (470) 641-2562

⚠ WARNING

Arc Flash and Shock Hazard. Appropriate PPE Required!

PNL_COMPLEX (WC)

0.37 cal/cm^2 @18 in		**27.75 kA**	Fault Current
9 in	Arc Flash Boundary	**0.010 sec**	Trip Time
415 VAC	Shock Hazard		
42 in	Limited Approach		
12 in	Restricted Approach		
00	Glove Class		

SHAW
CONSULTING SERVICES, LLC

WWW.SHAWENGR.COM

Minimum PPE Requirements:

NON AR Arc-rated or nonmelting untreated natural fiber clothing, Rubber insulating gloves and leather protectors, Hard hat, Safety glasses or goggles, Hearing protection, Leather footwear.

04/23/2026

SHAW CONSULTING SERVICES, LLC. (470) 641-2562

⚠ WARNING

Arc Flash and Shock Hazard. Appropriate PPE Required!

SWGR_FEDERAL PACIFIC (WC)

29.0 cal/cm^2	**@36 in**	**7.66 kA**	Fault Current
177 in	Arc Flash Boundary	**0.179 sec**	Trip Time
34500 VAC	Shock Hazard		
72 in	Limited Approach		
31 in	Restricted Approach		
4	Glove Class		

SHAW CONSULTING SERVICES, LLC

WWW.SHAWENGR.COM

Minimum PPE Requirements:

Clothing with an arc-rating > the incident energy. Long-sleeve shirt + pants or coverall or arc flash suit. Arc-rated arc flash suit hood. Arc rated outerwear as needed. Arc-rated gloves, Hard hat, Safety glasses or goggles, Hearing protection, Leather footwear.

04/23/2026

SHAW CONSULTING SERVICES, LLC. (470) 641-2562

⚠ WARNING

Arc Flash and Shock Hazard. Appropriate PPE Required!

SWGR_VISTA (WC)

323.7 cal/cm^2 @36 in		**7.67 kA**	Fault Current
592 in	Arc Flash Boundary	**2.000 sec**	Trip Time
34500 VAC	Shock Hazard		
72 in	Limited Approach		
31 in	Restricted Approach		
4	Glove Class		

SHAW CONSULTING SERVICES, LLC

WWW.SHAWENGR.COM

Minimum PPE Requirements:

Clothing with an arc-rating > the incident energy. Long-sleeve shirt + pants or coverall or arc flash suit. Arc-rated arc flash suit hood. Arc rated outerwear as needed. Arc-rated gloves, Hard hat, Safety glasses or goggles, Hearing protection, Leather footwear.

04/23/2026

SHAW CONSULTING SERVICES, LLC. (470) 641-2562

⚠WARNING

Arc Flash and Shock Hazard. Appropriate PPE Required!

XFMR_SEC (WC)

40.8 cal/cm^2 @18 in		**31.20 kA**	Fault Current
163 in	Arc Flash Boundary	**0.993 sec**	Trip Time
415 VAC	Shock Hazard		
42 in	Limited Approach		
12 in	Restricted Approach		
00	Glove Class		

SHAW CONSULTING SERVICES, LLC

WWW.SHAWENGR.COM

Minimum PPE Requirements:

Clothing with an arc-rating > the incident energy. Long-sleeve shirt + pants or coverall or arc flash suit. Arc-rated arc flash suit hood. Arc rated outerwear as needed. Arc-rated gloves, Hard hat, Safety glasses or goggles, Hearing protection, Leather footwear.

04/23/2026

SHAW CONSULTING SERVICES, LLC. (470) 641-2562